

Rev. 2-15-61

P.I. YES GUN EXAMINATION REPORT NUMBER: 202 MODEL: 600
 GENERAL CONDITION: FAIR R #: 33722
 OUTSIDE WORK: RECOIL PAD ADDED STOCK DATE: 12-17-70
CUT OUT BY REAR SIDE - Material added FROM: McBride Gun
Stock in padding 307 + F.V. 2418
 FIRED AMMO TYPE: NOT KNOWN JUSTIN TEX.
 & CONDITION: _____ GUN #: 6670372
 PROOF: REP INSP.: 93 TEST: 70 CODE: XX-12-73
 HEADING: _____ GA./CAL.: 243
 BREACH OPENING: _____ CHECKED BY: McHardy
 RECOIL SHOULDERS: _____ APPROVED: 9/29/70
 CHAMBER: _____ APPROVED: 1/29/70
 TEST: _____ APPROVED: 1/29/70
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 1-29-E

TOO DENTED, CUT OUT BY REAR SIDE SCREWS

SCREW HOLES RECOIL PAD ADDED

1" V" on trigger assembly

COMPLAINT: SHOT HOLE THROUGH FLOOR

INCIDENT: _____

COMMENTS: Passes tick test. Sear lift .0075"
Engagement OK, adjusting screws have not been
tightened with.
Unable to produce any trigger assembly malfunctions

N160