

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 19, 1990

Mr. H. Patrick McCaffrey
3304 Olympic Circle
Nixa, Missouri 65714

Dear Mr. McCaffrey:

We have completed examination of your rifle which was returned to us on December 1, 1989 along with your letter dated November 28, 1989, and the enclosures. We apologize for the delay in responding to your correspondence. We have been busy servicing our customers requests following the end of the fall hunting season. In addition, we wanted to carefully consider the statements made in your letter.

Examination of your rifle revealed that it operated properly in every respect. Trigger pull was measured to be 5 pounds and the sear-lift with the safety in the "on-safe" position was within specifications at .008". It was noted that the original trigger assembly has been replaced with one which allows the bolt to be raised when the safety is in the "on-safe" position.

We found nothing wrong with your rifle and, therefore, have decided that we will not comply with your request to provide you with a new firearm. Remington has been involved in litigation as you note concerning allegations regarding the Model 700. However, we stand behind both examinations of your rifle. On both occasions, numerous attempts were made to duplicate the malfunctions described in your 1984 letter without any accidental firings experienced.

✓ Dec. Arms Service
R89-29112
Return Rifle as-is
J. Hutton, F. Supply
R89-29112