

January 23, 1985

Remington Arms Company, Inc.
J.A. Stekl, Supervisor
Product Service
Ilion, New York 13357

Dear Mr. Stekl:

Thank you for your response to my letter of November 29th. Enclosed is the rifle shipped per your instructions.


You indicated that accidental firings result from either improper adjustment of the trigger assembly, improper maintenance, or from pressure inadvertently applied to the trigger as the safety is being moved. I can assure you that with the exception of mounting a scope and a sling, nothing has been modified or tampered with. It has been fired very infrequently and used only during deer season. As far as maintenance, only the barrel and bolt areas have been cleaned after usage. The trigger assembly has never been touched.

You may send repaired rifle to:

Patrick McCaffrey
#5 Bramble Woods Lane
Rt. 3, Box 40-5
Nixa, MO 65714

I appreciate your philosophy of standing behind the products which Remington markets.

Sincerely,


Patrick McCaffrey