

RECEIVING AND ESTIMATING REPORT

COMMENTS

Stekl

ORDER  
R92-19540

INITIAL CUSTOMER ORDER NO.

PS

|               |             |            |               |                   |                 |
|---------------|-------------|------------|---------------|-------------------|-----------------|
| DATE RECEIVED | DATE OPENED | DATE CODE  | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
| 19/16/92      | 09/28/92    | DS 9-69    | 6273958       |                   | 700 270 WIN BDL |
| ACCESSORIES   | W/STUDS     | SCOPE BASE | L/SIGHTS      |                   |                 |

FROM:

SHIP TO:

MCCLELLANDS GUN SHOP  
DIVISION OF REMCO  
1533 CENTERVILLE ROAD  
DALLAS TX 75228

MCCLELLANDS GUN SHOP  
DIVISION OF REMCO  
1533 CENTERVILLE ROAD  
DALLAS TX 75228

CUST NO:006612 WILM

|                |                    |                                           |            |           |     |
|----------------|--------------------|-------------------------------------------|------------|-----------|-----|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> CLEAN/TEST | PROM. DATE | ESTIMATED | VIA |
|                |                    |                                           |            |           | UPS |

GUN CONDITION  
☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| NOISE            | A1   | B1       |        |          |     |         |
| TRIGGER GROUP    |      | B2       |        |          |     | F1      |
| BOLT ASSY.       |      | B3       |        |          | E2  | F2      |
| BARREL ASSY.     |      | B4       |        | D1       | E3  | F3      |
| REC. ASSY.       |      | B5       |        | D2       | E4  | F4      |
| WOOD             |      |          | C1     | D3       | E5  | F5      |
| METAL            |      |          | C2     |          |     |         |

MAIN FAULT

Could not duplicate complaint after many attempts. Rifle trigger assembly operates properly in every respect. Trigger pull of rifle did reveal that trigger assembly has been adjusted out of balance - original balance has been replaced on weight of pull of vertical adjusting screw - over travel is inadequate.

Trigger pull - 3 1/2 pounds & rear lift "002"

ARTS

COMMENTS

We can either properly adjust present trigger assembly, or install new trigger assembly at 3 round cost, even though there is nothing wrong with present assembly as a system of good-will, if that will better customer confidence in the rifle.

Offer customer above system

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| KBS            |       |       |      |        |         |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |