

BARBER - Kinzer PPS GAL RE0003306

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R 94-02337																									
INITIAL		CUSTOMER ORDER NO.																													
FPS																															
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE																										
01/18/94	01/19/94	LD 2-77	A6413886		700 30-06		BDL																								
ACCESSORIES		W/STUDS																													
FROM:				SHIP TO:																											
<i>F. Supply</i> MCCLELLANDS GUN SHOP DIVISION OF REMCO 1533 CENTERVILLE ROAD DALLAS TX 75228				MCCLELLANDS GUN SHOP DIVISION OF REMCO 1533 CENTERVILLE ROAD DALLAS TX 75228																											
L				L																											
CUST NO: 006612 WILM																															
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		PROM. DATE		ESTIMATED																									
						VIA UPS																									
GUN CONDITION		<i>Product Service</i>				REPAIR CHARGE																									
☐ NEW						25.00																									
☐ LIGHTLY WORN						EXCISE																									
☐ WORN						TAX																									
☐ VERY WORN						INSURANCE																									
☐ UNREPAIRABLE						UPS																									
☐ MARRED						PARCEL POST																									
						TOTAL																									
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT																									
CYCLE		B1																													
TRIGGER GROUP		B2			F1	F1																									
BOLT ASSY.		B3			E2	F2																									
BARREL ASSY.		B4		G1	F3	F3																									
REC. ASSY.		B5			F4	F4																									
WOOD		C1			F5	F5																									
METAL		C2																													
MAIN FAULT: <i>Upon receipt, unable to duplicate customer concern. Examination revealed that the trigger adjustment screw had been fully retracted causing the stop screw to engage and prevent movement. Customer adjusted non-fact. Subsequent inspection revealed 009</i>																															
PARTS		COMMENTS																													
		<i>4 1/2 in. Repair complete trigger assembly with no bolt lock, and then action is 1/2 normal replacement cost. adjusted & good will</i> <i>Go ahead</i>																													
		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>REPAIRMAN</td> <td>PROOF</td> <td>CLEAN</td> <td>TEST</td> <td>TARGET</td> <td>PATTERN</td> </tr> <tr> <td><i>P.C.</i></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>GALLERY TESTER</td> <td>DATE</td> <td>DATE</td> <td>DATE</td> <td>DATE</td> <td>DATE</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>						REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	<i>P.C.</i>						GALLERY TESTER	DATE	DATE	DATE	DATE	DATE						
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN																										
<i>P.C.</i>																															
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE																										

OFFICE COPY

RD6925 REV. 1/92