

Remington



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 19, 1990

McClelland Gun Shop
1533 Centerville Rd.
Dallas, TX 75228

Dear Sir:

Examination has been completed on the Model 700 Classic 270 Win. caliber rifle, serial number A6780418, that you returned to us a short time ago because, "customer complaint: gun fires when pushed off...".

The returned firearm, which was produced in August of 1979, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had passed all necessary tests and inspections before being shipped from our factory.

The general condition of the gun appeared to be good, however, it was noted that the stock contained many scratches and mars. In going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal. Trigger pull was measured to be 5 1/2 pounds and the sear-lift with the safety in the "on-safe" position was within specifications at .012".

Examination of the rifle and trigger assembly could not duplicate the customer reported malfunction. Many attempts were made to cause the rifle to fire upon moving the safety from the "safe" to "fire" position, but it would not malfunction. The only way the rifle could be made to fire was with the safety in the "fire" position and the trigger pulled, functioning as designed.