

M/700 Cigarette  
Company

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL  
 GENERAL CONDITION: NEW R #: 013324  
 OUTSIDE WORK: NO DATE: 7-6-72  
 FROM: MEYER HOWE & SPTGS. INC.  
 FIRED AMMO TYPE: \_\_\_\_\_ GOLDEN, COLO.  
 & CONDITION: \_\_\_\_\_ GUN #: 6230255  
 PROOF: R.E.P. ASSEMBLER 813 INSP.: 73 TEST: 87 CODE: AS = 3/69  
 HEADING: \_\_\_\_\_ GA./CAL.: 6 MM REM.  
 BREACH OPENING: - CHECKED BY: C. PROSSER  
 RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: NO APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

CONNECTOR CLEARANCE ON TRIGGER .004 UNDER MIN. & OF  
PIN TO TOP OF TRIGGER ON MAX. TRIGGER HITS TRIGGER  
HOUSING. HEAVY LUBRICANT USED INSIDE HOUSING.  
SAFETY P. .001 UNDER MIN. CONNECTOR CAPTIVES ON SEAR  
WITH SAFETY ON.

COMPLAINT: "HAMMER FALLS"

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF LOW SAFETY, HIGH TRIGGER  
AND TRIGGER BIND CAUSES FAILURE TO RETRACT WHEN  
TRIGGER IS PULLED WITH SAFETY ON, THEN FOLLOW  
DOWN WHEN SAFETY IS PUSHED OFF.