

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-01047

INITIAL CUSTOMER ORDER NO.

ATTN DENNIS SANITA

JJM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/07/94	01/10/94	BA 1-B0	A6B73380		700 270 - BDL
ACCESSORIES W/STUDS SCOPE BASE					

FROM:

Miller, John
MILLER, JOHN
2 MILES HWY 77A
BOX 384
ROBSTOWN TX 78380

SHIP TO:

MILLER, JOHN
2 MILES HWY 77A
BOX 384
ROBSTOWN TX 78380

CUST NO: 090247 C-B.O.L

TX 78380

ACCOUNT NUMBER	ACCOUNT NUMBER I/C	PROM. DATE	ESTIMATED	VIA
				UPS

RUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☒ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	25.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Left May 1980, not subject to call back. Unable to duplicate
function. Found that the action and trigger assembly are covered
with a sticky gunny substance. The bolt stop, release and cam spring
are all working properly. Left for gun shop maintenance.

ARTS

COMMENTS

Left for gun shop maintenance.

Replace trigger assembly
and other action at gun shop
replacement cost, as per order of gun shop.

Go ahead

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 1/92