

DECEMBER 26, 1985

MR. L. J. MOORE

P.O. Box 179

FOLLOESVILLE, NC 28573

Dear Mr. Moore:

Your letter of December 12, 1985 that was sent to our Goldsboro, North Carolina facility, concerning the accidental firing you experienced with your Model 700 220 Winchester caliber rifle, has been received and entered in this office for handling.

We have indeed made a determination as to the cause of the firing and, incidentally, it is not representative of Remington-Union City, nor characteristic of the Model 700 rifle.

Generally, the type of incident as described usually occurs with improper adjustment of the trigger assembly, which can be caused by improper maintenance of the rifle, or by inadvertent contact to the trigger.

Please let your manufacturer, Remington-Union City, Inc., transmission S.O.D. 700.

Respectfully,
Sincerely,
Product Training Division

Product Training Division

Product Training Division

Product Training Division

I am to believe that the cause of the firing of the rifle is due to the trigger assembly, to specific loading.

Very respectfully,
Product Training Division

Very respectfully,
Product Training Division