


During the sighting in process during the second plus incidents, about fifteen shots in total had been fired.

I have not done anything, including cleaning, to the rifle after the sighting in incidents as I wanted you to have the rifle as is. The rifle which performed well up to now is unpredictable and dangerous.

I would appreciate your repairing the rifle and informing me of the nature of the problem.

Sincerely,



Ronald A. Munier
9617 Longmont
Houston, Texas 77063
(713) 784-4348