

DATE: May 19, 1994

TO: Remington Arms Co.  
Dept. 700  
14 Hoefler Ave.  
Ilion, NY 13357

FROM: Michael Mutarelli  
835 Hickory Road  
Walnutport, Pa. 18088

RE: Recall of Model #700 for Repair of Trigger Mechanism

As per my conversation with Pat, I am enclosing my Remington Model #700 ADL: Serial #B6630223; .30-06 caliber, bolt action rifle to have the trigger mechanism repaired or replaced because of a possible defect that may or may not cause bodily injury and/or death.

Some of the problems I have encountered with the weapon was a delay of approximately 15 seconds in firing, and an occasion where the weapon would not fire at all with the safety off and the trigger pulled.

I trust you will return the sporting arm in a timely manner as I am quite anxious to practice with it for the upcoming deer season.

Thank-you.