

Customer Complaint.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: FAIR R #: 12988
OUTSIDE WORK: SCOPE MOUNTED DATE: 6-28-71
FROM: NAT. PARK SERV.
FIRED AMMO TYPE: - KAHULUI, MAUI, HAWAII
& CONDITION: _____ GUN #: 6258663
PROOF: R.E.P.-E ASSEMBLER 64 INSP.: U TEST: 87 CODE: 05 = 7/69
HEADING: O.K. G.K./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS.CONNECTOR CLEARANCE ON TRIGGER 1.062 M/D = $\frac{1.079}{1.070} - .014$ TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = $\frac{1.083}{1.080} + .004$ CONNECTOR-SEAR ENGAGEMENT .025 - O.K.COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE THE CUSTOMER'S MALFUNCTION.
THE TRIGGER CONNECTOR & TRIGGER NOT TO MODEL
DRAWING PERMIT SEAR, CONNECTOR INTERFERENCE,
FAILURE TO RETRACT.