

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 12986
 OUTSIDE WORK: SCOPE MOUNTED DATE: 6-28-71
 FROM: NAT. PARK SERV.
 FIRED AMMO TYPE: - KAHULUI, MAUI, HAWAII
 & CONDITION: _____ GUN #: 6258726
ASSEMBLER 64
 PROOF: R.I.P.-F INSP.: U TEST: 87 CODE: 05 = 7/69
 HEADING: O.K. GA./CAL.: 3006
 BREACH OPENING: F CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO COMPONENT BROKEN.

CONNECTOR CLEARANCE ON TRIGGER = 1.070 M/D = $\frac{1.079}{1.070} - .009$

TRIGGER CLEARANCE ON CONNECTOR = 1.090 M/D = $\frac{1.083}{1.090} + .010$

CONNECTOR - SEAR ENGAGEMENT O.K.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.

THE TRIGGER CONNECTOR - TRIGGER NO - TO
MODEL DRAWING, PERMIT SEAR, CONNECTOR
INTERFERENCE - FAILURE TO RETRACT.