

-2-

Since we found the trigger assembly to be contaminated and outside our specifications, we can either clean and readjust the present assembly or, if it will better restore your confidence in the rifle, we will install a new trigger assembly at no-charge (either option is subject to \$10.00 handling plus return shipping fee). We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,



J.A. Stekl, Specialist
Product Service

JAS:tp