

RECEIVING AND ESTIMATING REPORT						COMMENTS	
INITIAL FPS		CUSTOMER ORDER NO.				ORDER R 94-06417	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
02/15/94	02/21/94	ET 10-70	6373088		700 7MM MAG	SS/BDL	
ACCESSORIES		SCOPE BASE		L/SIGHTS			
FROM:				SHIP TO:			
NICODEMUS, WILLIAM 10524 VINEMONT ST DALLAS TX 75218				NICODEMUS, WILLIAM 10524 VINEMONT ST DALLAS TX 75218			
CUST NO: 092669 C-D-D-L							
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE	FROM DATE	ESTIMATED	VIA UPS
GUN CONDITION						REPAIR CHARGE 20.00	
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS 5.00 PARCEL POST TOTAL 125.00	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	Fixed action safe was taken					
TRIGGER GROUP	B2	Fixed as I took it off					
BOLT ASSY.	B3						
BARREL ASSY.	B4			D1	E3	F3	
REC. ASSY.	B5			D2	E4	F4	
WOOD				C1	E5	F5	
METAL				C2			
MAIN FAULT: Left rif. 1970 purchased used per plan, was shot in other town with rif. (plan 3/28/94) Upon receipt could not duplicate function. However, manufacturer wanted that the action and trigger assembly be replaced with a factory replacement. But shop where unit was shot.							
PARTS				COMMENTS			
				Replace trigger assembly & clean action at 42,000 rpm. Parts in good condition.			
				Exp.			
MC 5420 3961 3720 1698 5/96				Go ahead			
Phone 214-319-9163							
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
DATE	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY

RD0925 REV. 1/94