

R ORDER
92-04497

FROM:	SHIP TO:
NORTHERN IOWA SPORTS SUPPLY	NORTHERN IOWA SPORTS SUPPLY
NORTHERN IOWA SPORT SHOP	NORTHERN IOWA SPORT SHOP
12 7TH AVE SE	12 7TH AVE SE
WAUKON	WAUKON
IA 52172	IA 52172

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			F1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

1.) trigger pull measured at 2# - well below the minimum spec. (2) insuff over travel; 3.) excessive rear engagement. In addition to the above, the extremely light trigger pull resulted in improper operation of the trigger spring - the trigger does not re-set upon cocking. Trigger assembly not operating properly as received.
Trigger pull 2 pounds; rear-leaf .011"

OFFICE COPY

RD6925 REV