

INITIAL FPS	CUSTOMER ORDER NO.	
DATE RECEIVED 11/27/91	DATE OPENED 12/03/91	DATE CODE XD 12-83
SERIAL NUMBER B6529376		NEW SERIAL NUMBER
MODEL AND GRADE 700 270 WIN		BDL
ACCESSORIES W/STUDS		

L/REAR SIGHT

FROM:

OLAVARRI, MARTIN
812 EMERALD BAY RD
S LAKE TAHOE
USA

CA 96150

SHIP TO:

OLAVARRI, MARTIN
812 EMERALD BAY RD
S LAKE TAHOE
USA

CA 96150

CUST NO: 053971 C.O.D L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	-------------------

- GUN CONDITION
- ☐ NEW
 - ☐ LIGHTLY WORN
 - ☐ WORN
 - ☐ VERY WORN
 - ☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Not able to duplicate above complaints. Trigger and safety assembly operates properly in every respect. Trigger pull measured at 5 1/4 pounds; 2-in-lift 0.10". However, it was noted that trigger assembly and bolt stop were chattering wet with excessive oil. This condition coupled with cold temperatures could conceivably cause internal trigger parts to hang-up.

PARTS

COMMENTS

Offer to clean present trigger assembly or replace trigger assembly at \$100.00 as good-will gesture, if it will better restore confidence in the rifle.

REPAIRMAN B5F	PROOF	CLEAN	TEST	TARGET	PATTE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8