

Dear Remington

A number of years ago this rifle was returned to you because when the bolt is seated in the cocked position sometimes the firing pin would follow it forward. in other words the rifle would not cock. other times it would cock momentarily then the pin would fire without touching the trigger. I have not fired this gun since that time believe it or not, it must be 10 yrs. But last week I picked it up & sure enough I still have the same problem.

Sincerely

Harold Ollivier

15 Oakesdale Manor

Suffern, N.Y.

10901

I feel of recall correctly this was first returned on a manufacturers recall. Because of this problem