

RECEIVING AND ESTIMATING REPORT

CUST NO: 002733 ILION		COMMENTS STOCK NOT OF OUR MFG W/OWNERS MANUAL	
TITLE PS	CUSTOMER ORDER NO.		
DATE RECEIVED 9/05/91	DATE OPENED 08/09/91	DATE CODE KW 5-72	SERIAL NUMBER 6555426
MODEL AND GRADE 700 270 WIN		ORDER R 91-15427	

ACCESSORIES: W/STUDS SCOPE BASE L/REAR SIGHT

FROM: OUTDOORSMAN
1011 MAIN STREET
HOPKINS MN 55343
USA

SHIP TO: OUTDOORSMAN
1011 MAIN STREET
HOPKINS MN 55343
USA

COUNT NUMBER ACCOUNT NUMBER N/C WRITE ☐ CLEAN/TEST PROM. DATE ESTIMATED VIA UPS

PAIR CHARGE TAX INSURANCE UPS PARCEL POST TOTAL

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: "Our customer says, several times, the gun res fired when taking it off safety"

MAIN FAULT: Cannot duplicate complaint, however, it was noted trigger part movement is very slow. Trigger assembly is contaminated with gummy residue. This condition coupled with cold temperature could cause problems. Trigger assembly has been adjusted outside factory - redant missing from adjustment screws.

REPAIRMAN: [Signature] PROOF CLEAN TEST TARGET PATTERN
GALLERY TESTER DATE DATE DATE DATE DATE DATE

OFFICE COPY

RD6925 REV. 7/90