

1 UNIT ONLY - WHITE

To _____

Date _____

From _____

MODEL CALB. R-No. PICK UP No. SER No DATE

700 ADL 212 REM 28870 180 A6524535 11-28-79

FIRE CONTROL APPEARS TO HAVE BEEN TAMPED
WITH SEAL LEADS FOREIGN. TRIG. PULL W/18) OPEN BPA
OUT OF SPEC

1 COULD NOT CHECK HEADING DUE

TO FURTHER INTERFERENCE, WILL NOT SEE GUN.

EVEN 10 BOLT FACE ???

RIFLE HOLLOWS DOWN SAME MESS DUE TO 11000 ADL

ON 20 78104 TEST

SAFETY IS A WISE INVESTMENT

ON SCREEN DOWN TEST

John Whitehead