

THE PALMOUR GROUP

November 10, 1993

[Handwritten signature]

Remington Arms Company, Inc.
Product Service
14 Hoefler Avenue
Ilion N. Y. 13357

RECEIVED
NOV 16 1993

HAROLD H. PALMOUR
DORTHA M. PALMOUR

REC
NOV 16 1993
PRODUC

Attention Mr. Sonita

Dear Mr. Sonita,

Re my telephone conversation of November 9, 1993, concerning my Model 700 rifle.

The problem is it will fire when chambering a round or when a safety is pushed forward.

I shipped it to your attention by U.P.S. today and you should receive it Friday, November 12, 1993, or Monday, November 15.

Please advise what caused the problem and what you can do to fix it. We are very fortunate no one was injured because of this malfunction.

Sincerely,

[Handwritten signature: Harold Palmour]
Harold Palmour

1 Copy - File

~~ROUTE 8 BOX 428~~ 4565 FM 3126
LIVINGSTON, TX 77351-9104

(409) 566-4033 OR (409) 967-8885
MOBIL PHONE (409) 327-0861