

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

October 29, 1984

Mr. Robert B. Parker  
12207 Ponca Rd.  
Omaha, Nebraska 68112

Dear Mr. Parker:

Your letter of October 19, 1984 that was addressed to our Bridgeport, Connecticut facility, regarding the accidental discharge you experienced with your Model 700 LH BDL rifle, serial number 6761350, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you related, as it is not representative of Remington quality, nor characteristic of the Model 700 rifle.


Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger as the safety is being moved. *I Also stated, magazine will not hold three (3) cartridges. Please ck. out.*  
Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Co., Inc.  
Attn: J.A. Stekl, Supervisor  
Product Service  
Ilion, N.Y. 13357

Upon receipt, we will thoroughly examine the rifle and, if it is found to be factory faulty, any necessary repairs will be made on a no-charge basis.

Thank you for bringing this matter to our attention and for affording us this opportunity to be of service to you.

Sincerely,

  
J.A. Stekl, Supervisor  
Product Service

JAS:tp