

HERB PARKHURST
GUNS, SCOPES, AMMO.
ELMORE RD., MORRISVILLE, VT.
888-2382

Repair Service

You may have heard
all kinds of stories, but
this is how my
customer told me.
This model 700
never functioned
properly. This customer
was hunting in
Colorado 1988. The
gun fired into the
ground when he released
the safety. He tried
to fix it that night
in camp, but broke
a trigger adjustment
screw. The gun
appeared to function
at this point. The