

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 29, 1988

Mr. Laurie Parpart  
311 Colorado  
Laurel, Mont. 59044

Dear Mrs. Parpart:

Your recent letter that was addressed to our Bridgeport, Connecticut facility, regarding the accidental firing you experienced with your 30-06 caliber rifle, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of any kind with one of our (?) products.

While you did not mention a specific Model of rifle in your letter, we assume it is either a Model 700 Classic or Model 700 BDL, since you did refer to "dropping the floor plate".

The recall that Remington made nine (9) years ago was for the Model 600 and 660 series rifles. The Model 700 rifle does not have a like problem and has never been recalled.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from accidental contact with the trigger when the safety is in the "fire" position.

If you desire, we would gladly examine the rifle to insure proper operating condition. If so, please return the rifle via U.P.S. insured to:

Remington Arms Co., Inc.  
14 Hoefler Ave.  
Ilion, NY 13357  
Attn: Arms Service Division