

December 7, 1981

Dear Sirs,

I recently purchased this 700 Classic from a dealer here in West Virginia and I am very disappointed with the work. I would like to have it replaced. I would like for you to check the action also. We first and sometime the second time you work the action it will disassemble.

Thank You,

Philip Parsons
Philip Parsons

P.P.L.# 55-020-01-02-07005

P.S. You have a current copy of my P.P.L. file.