

MAR 31 1994

MARCH 28, 1994

REMINGTON ARMS CO, INC  
PO BOX 179  
ILION, NEW YORK 13357

SIRS:

PLEASE REFER TO REPAIR ORDER 92-03077, WHICH INDICATES THAT I RETURNED ONE MODEL 700 BOLT ACTION RIFLE (30-06) AND INDICATED THAT THE RIFLE HAD FIRE ON THREE SEPARATE OCCASIONS UPON RELEASING THE SAFETY IN PREPARATION TO UNLOAD THIS GUN. AT THAT TIME YOU INDICATED THAT YOU COULD NOT CAUSE THE GUN TO REPEAT THIS CONDITION, BUT CHANGED OUT THE BOLT MECHANISM. AS A DISPLAY CONCERN AND GOOD FAITH.

DURING THE PAST HUNTING SEASON, 1993-1994, THE GUN AGAIN FIRED DURING MY UNLOADING IN THE FIELD; THIS TIME MY HUNTING BUDDY, W D MORROW, WAS ALMOST SHOT. (HE CAME HOME AND TOLD HIS WIFE, WHO TOLD MY WIFE WHO GAV ME A HARD TIME). I HAVE LOST FAITH IN THIS WEAPON AND CANNOT USE IT FOR THIS REASON.

I HAVE HAD SEVERAL REMINGTON PRODUCTS THROUGHOUT THE YEARS AND HAVE A GREAT DEAL OF CONFIDENCE IN THEM, HOWEVER DO NOT HAVE ANY CONFIDENCE I THIS GUN.

I PROPOSE THAT I SEND YOU THIS GUN, SERIAL # A-6346902, AND YOU REPLAC IT WITH A SIMILAR WEAPON. (I ALSO HAVE A MODEL 742, WHICH HAS ALWAYS PERFORMED WELL, WITH NO PROBLEMS).

BEST REGARDS  
*Clayton L. Payne*  
CLAYTON L PAYNE  
1360 GIBSON DRIVE  
BIRMINGHAM, AL 3521

*3/31/94*

*Called Mr. Payne -*

*Agreed to have picked up for repair. Call tray would*