

Cust. Complaint.

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: Good R #: 27191
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-27-71
 FROM: PECOS SPT GDS.
 FIRED AMMO TYPE: - PECOS, TEXAS
 & CONDITION: _____ GUN #: 638 3773
 PROOF: PEQ-A INSP.: 73 TEST: 27 CODE: RT = 11/70
 HEADING: O.K. GA./CAL.: 2506 REM
 BREECH OPENING: - CHECKED BY: C. PROCTOR
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-CONNECTOR ENGAGEMENT .030, TRIGGER PULL 2 1/2
POUNDS, STOCK ETC. NOT INCLUDED, MARK ON TRIGGER
SIDE INDICATES POSSIBLE BIND ON TRIGGER GUARD.

NO STOCK, MAGAZINE OR MAGAZINE FOLLOWUP &
SPRING.

COMPLAINT: DISCHARGED WHEN SAFETY WAS MOVED FROM SAFE
TO FIRE POSITION.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED,
HOWEVER IT MAY HAVE BEEN CAUSED BY TRIGGER BINDING
IN THE TRIGGER GUARD.