

RECEIVING AND ESTIMATING REPORT

INITIAL **FPS** CUSTOMER ORDER NO. **94-13438** ORDER **R**

DATE RECEIVED **04/18/94** DATE OPENED **04/19/94** DATE CODE **RE 11-84** SERIAL NUMBER **7639670** NEW SERIAL NUMBER **7** MODEL AND GRADE **7MM-08**

ACCESSORIES **W/STUDS** SCOPE BASE **L/REAR SIGHT**

FROM: **PENN, RON
1111 ROUTE 6N
WATERFORD PA 16441**

SHIP TO: **PENN, RON
1111 ROUTE 6N
WATERFORD PA 16441**

CUST NO: **096164 CLO.D**

ACCOUNT NUMBER **WRITE** FROM DATE **ESTIMATED** VIA **UPS**

GUN CONDITION
☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE **20.00**
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Upon receipt could not duplicate concern. However, examination reveals a thick layer of grease substance inside the trigger housing and on left side of the receiver. Once cleaned and tested, pull adjustment seems to have been OK. Mfg. 1984*

PARTS *# 92455 Trigger Assembly
92458*

COMMENTS *Trigger pull measured 3 1/2 to 3 3/4 lbs. all stock. Saw left was .914. Positive complete trigger assembly and clean action at 1/2 normal adjustment. Act. in quarter of foot will.*

REPAIRMAN **TAL** PROOF **CLEAN** TEST **DATE** TARGET **DATE** PATTERN **DATE**

GALLERY TESTER **DATE** DATE **DATE** DATE **DATE** DATE **DATE**

OFFICE COPY

RD6925 REV. 1/84