

BARBER - Kinzer PPS GAL RE0003885

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 13298
 OUTSIDE WORK: No DATE: 6-29-71
 FROM: J.C. PENNEY
 FIRED AMMO TYPE: - KING OF PRUSSIA, PA.
 & CONDITION: ASSEMBLER 79 GUN #: 6274124
 PROOF: R.E.P.-E INSP.: 58 TEST: 13 CODE: DS = 9/69
 HEADING: O.K. GA./CAL.: 270
 BREECH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS.

TRIGGER CONNECTOR - SEAR ENGAGEMENT .010 (.020 MIN.)

TRIGGER PULL 4 1/2 LBS. A SMALL METAL CHIP CAUGHT BETWEEN TRIGGER CONNECTOR & TRIGGER.

COMPLAINT: "FIRES DURING SHELL EXTRACTION"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. THE UNDER MIN. ENGAGEMENT WAS CAUSED
BY THE METAL CHIP (HELD IN PLACE BY A PROTECTIVE
COATING APPLIED BY THE CUSTOMER) PROBABLY CAUSED
THE MALFUNCTION.