

Dennis
SL 015 / T.P. 5 # 12/31
SEAR In Not Responsive
Sticky Gummy Brown Residue
On Bow Drop Release Sealant
Present Front & Rear Replace
~~Fire~~ Trig Assy & Price
Cannot Duplicate ∇ Mant