

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
JJM							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER		
11/29/90	12/04/90		A6775475	700 7MMAG BDL/LH	R	90-313E	
ACCESSORIES		W/STUDS					

PV 6-79 2ND TIME IN

FROM:

PIDGEON ROAD SHOOTING RANGE
ROUTE 4 BOX 257
STEPHENVILLE TX 76401

SHIP TO:

PIDGEON ROAD SHOOTING RANGE
ROUTE 4 BOX 257
STEPHENVILLE TX
76401

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

"... The gun discharges when safety is moved from safe to fire."

MAIN FAULT

Cannot duplicate complaint. However, firing pin will sometimes follow-down when bolt is closed properly. Trigger assembly has been completely mis-adjusted outside factory, as evidenced by foreign sealant. Trigger pull below min. spec ($> \frac{1}{2}$ #), rear engagement inadequate, over-travel inadequate.

PARTS

Send quotation for replacement trigger assembly

Customer should be told not to attempt adjustments to trigger assembly!!!

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD0925 REV. 7/90