

NO. 100 4/78

Remington.

REPAIR

RHS:RT 3/1/88 29 ARMS SERVICE FILE

HASTY REPLY & CHECK

REMINGTON ARMS COMPANY, Inc. OR N.O. Remington.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

PLEASE MAIL
REMITTANCE
TO BOX CHECKED☐

BRIDGEPORT, CONN. 06402

☒

ELIOT, N. Y. 13357

INVOICE NO R-88-05101

INVOICE DATE

SHIP TO

SOLD
TOFalse River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

OUR ORDER NO R-88-05101-700

OUR ORDER NO

SHIP VIA UPS

DO 9-86

700 7MM MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.

MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking Rifle has been very poorly maintained.

1. 26345 Trigger assem. B.O.C.
2. Polished chamber
3. Test

TOTAL REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS

4.09

TOTAL CHARGES 44.09

THE REM-ARMS COMPANY, BRIDGEPORT, CONN. 06402

WE WILL BE GLAD TO REPAIR YOUR

FIREARM, AND WE WILL REPAIR IT AT THE LOWEST POSSIBLE COST. IF BY SIGNING BELOW, RETURN FIRST COPY

X TO REM-ARMS COMPANY, BRIDGEPORT, CONN. 06402, WE AGREE TO ACCEPT REPAIRS, TAKE ABOUT 4-6 weeks.

YOUR DEFECTIVE APPROVAL

CUSTOMERS SIGNATURE ▶

JUN 02 1988

CLEAN TEST TARGET

REPAIRMAN

OFFICE COPY

REM-725 REV. 3/84