

DUTY ARMS COMPANY, INC. OF N.Y.

Newington.

SPORTS WEAPONS, AMMUNITION, TARGETS AND TRAPS

BRIDGEPORT, CONN. 06605

WORK NO. A-88-05101

PLEASE MARK
DEFICIENCIES
TO BOX CHECKED

X NEW, N. Y. 13357

WORK DATE

USE TO

False River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

ADD TO

A-88-05101-700

SHIP VIA UPS

DU 9-86

700 TRM MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.

MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking. Rifle has been very poorly maintained.

1. 26345 Trigger assem. R.O.C.
2. Polished chamber
3. Test

MAY 05 1988

TOTAL REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS 4.09

TOTAL CHARGES 44.09

44.09

ALL WORK HAS BEEN RECEIVED AND IS IN FULL PAYMENT

REPAIRS WILL BE MADE APPROXIMATELY

4-6 weeks.

X

CUSTOMER'S SIGNATURE

CUSTOMER'S SIGNATURE

W. J. Murphy Jr. Kinzner

Please Ship gun

FOR COMPUTER REPLY

JUN 5 1988

CLEAN TEST TARGET

REPAIRMAN

RC0025 REV. 3-80