

REMINGTON ARMS COMPANY, INC. N.Y.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

Remington



PLEASE MAIL
REMITTANCE
TO BOX CHECKED

BRIDGEPORT, CONN. 06602

☒ ILION, N. Y. 13357

INVOICE NO R-88-05101

INVOICE DATE

SHIP TO

SOLD
TO

False River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

APR 22 1988

OUR ORDER NO R-88-05101-700

OUR ORDER NO

SHIP VIA UPS

DO 9-86

700 TDM MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.

MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking. Rifle has been very poorly maintained.

1. 26345 Trigger assem. N.O.C.
2. Polished chamber
3. Test

QUOTATION
TO REMINGTON ARMS CO., INC.

MAY 05 1988
Ar...

TOTAL REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS

4.09

TOTAL CHARGES 44.09

44.09

THE ITEM ABOVE HAS BEEN RECEIVED AND IS BEING REPAIRED

SHIPMENT WILL BE MADE APPROXIMATELY

THIS IS AN ESTIMATE TO REPAIR OR REPLACE THE ITEMS LISTED ABOVE TO SATISFACTION. PLEASE APPROVE BY SIGNING BELOW. RETURN 1st COPY

TO REMINGTON ARMS CO., INC., ILION, N. Y. RETAIN SECOND COPY AS YOUR RECEIPT. REPAIR TO 1st COPY 4-6 weeks.

AFTER RECEIPT OF APPROVAL

CUSTOMERS SIGNATURE *Christopher T. Dineen*

Please Trip gun

NOTE: IF YOU DESIRE ANY CHANGE IN SHIPMENT, PLEASE ADVISE US IMMEDIATELY.

FOR COMPUTER REPLY

JUN 3 1988

CLEAN TEST TARGET

REPAIRMAN

[Signature]