

RD 5396 - 8/78

Remington.



RBS:RT 1/1/88 20 ARMS SERVICE FILE AWAIT REPLY & CHECK

REMINGTON ARMS COMPANY, INC. OR H.O.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

Remington.

PLEASE MAIL
REMITTANCE
TO BOX CHECKED

BRIDGEPORT, CONN. 06602

X ILION, N. Y. 13357

INVOICE NO R-88-05101

INVOICE DATE

SHIP TO

SOLD
TOFalse River Sports Shop, Inc.
211 W. Main St.
New Roads LA 70760

OUR ORDER NO R-88-05101-700

OUR ORDER NO

SHIP: VIA UPS

DO 9-86

700 7MM MAG. BDL B6735295
W/studs, L/sights

COMPLAINT: When I pushed the safety forward, the rifle went off.

MAIN FAULT: Trigger assem. is full of rust & paint-assem. is so full of rust & paint that the trigger will not consistently return under sear-safety cam on cocking Rifle has been very poorly maintained.

1. 26345 Trigger assem. B.O.C.
2. Polished chamber
3. Test

TOTAL REPAIR CHARGE 40.00

INSURANCE

PARCEL POST

UPS

4.09

TOTAL CHARGES 44.09

THE FOLLOWING INFORMATION IS FOR YOUR INFORMATION ONLY. IT IS NOT A WARRANTY. APPROVE BY SIGNING BELOW. RETURN FIRST COPY.

IF YOU ARE NOT SATISFIED WITH THE REPAIR, WE WILL REPAIR IT FREE OF CHARGE. IF YOU ARE NOT SATISFIED WITH THE REPAIR, WE WILL REPAIR IT FREE OF CHARGE. IF YOU ARE NOT SATISFIED WITH THE REPAIR, WE WILL REPAIR IT FREE OF CHARGE.

IF YOU ARE NOT SATISFIED WITH THE REPAIR, WE WILL REPAIR IT FREE OF CHARGE. IF YOU ARE NOT SATISFIED WITH THE REPAIR, WE WILL REPAIR IT FREE OF CHARGE. IF YOU ARE NOT SATISFIED WITH THE REPAIR, WE WILL REPAIR IT FREE OF CHARGE.

CUSTOMERS SIGNATURE

JUN 12 1988

CLEAN, TEST, TARGET

REPAIRMAN

OFFICE COPY

REV. 3.88