

FROM THE DESK OF

Pro-Tec's Gun Shop

TOM SWINARSKI

2084 MIDLINE RD.

AMSTERDAM, N.Y. 12010

12/11/81

Remington

Dear Sir

Please check enclosed Rem 700

BOL 7mm mag # B6317842

*you off upon releasing
safety periodically*

Thanks

T.M.S.

24, 1982

7mm Rem. Mag.
turned to us
safety, period-

1981, has
it it contained
an inspection
and all our neces-

2. and it was
after it originally
in stock contained
we found the head-
all.

not duplicate the
and dimensions were
sent. Also, factory
indicating no al-
my. Trigger pull

cannot accept
any liability or responsibility for the accidents. It is possible
that while the safety lever was being moved from the "safe" to the
"fire" position, the trigger was inadvertently contacted. When the
safety lever reached the "fire" position, the gun then discharged - as
it is designed to do - because the trigger was being pulled with the
gun no longer on "safe".