

FROM THE DESK OF
✓ **Peor Tom's Gun Shop**

TOM SWINARSKI
RD#4 MIDLINE RD. AMSTERDAM, N.Y. 12010

Dear Sir:

*Please return
customer satisfied with
your findings*

*Thank
Tom S.*

MAR 1 1982

NY, INC.

ry 24, 1982

DL 7mm Rem. Mag.
returned to us
safety, period-

of 1981, has
that it contained
inal inspection
sued all our neces-

ood, and it was
after it originally
the stock contained
, we found the head-
rmal.

ld not duplicate the
s and dimensions were
ement. Also, factory
, indicating no al-
spany. Trigger pull

∴, cannot accept
any responsibility or compensation for the incident. It is possible
that while the safety lever was being moved from the "safe" to the
"fire" position, the trigger was inadvertently contacted. When the
safety lever reached the "fire" position, the gun then discharged - as
it is designed to do - because the trigger was being pulled with the
gun no longer on "safe".