

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS ATTN: J. STEKL					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER		
06/90	09/18/90	RZ 11-75	A6208763	600 243 MOHAWK	R 90-24056		
SLING STRAP		W/STUDS	W/SWIVELS	SCOPE BASE	L/SIGHTS		
W/ RECOIL PAD							
SHIP TO:							
PRIDGEN, LYNN RT 6 BOX 6366 PALESTINE TX 75801				MAIL & MORE 712 W OAK ST PALESTINE TX 75801			
ITEM NUMBER	ACCOUNT NUMBER N/C		WRITE ☐	PROM. DATE	ESTIMATED	VIA	
						UPS	

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☒ MARRED

ER'S REQUEST

.. it discharged when I took it off safely. ..

*ULT Could not duplicate complaint, however, disassembly revealed
part has been removed from all 3 trigger adjusting screws and
interior have been affected outside of factory - 1) no trigger adjustment
2) examine overhand 3) examine engagement*

*either re-adjust trigger assembly to
proper specification or if that is not
possible, send gun back for a normal
price to replace trigger assembly.*

*9/21/90
Jds.*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88