

Don
Sperry Electric
RT 109
Searched me 04012

Remington Arms Co. Problem

Customer Service

to remedy

Don't let for safety

Dear Sir,

I am returning the enclosed Remington 700 A02, 30-06, Serial 6887265 for repair of an extremely dangerous defect in the firearm's safety mechanism. On three separate occasions the gun has discharged when the safety was moved to the fire position. I have had the gun examined by a local gunsmith who tightened up the safety but could find no other problem. The gun has since malfunctioned since the "repair". Interestingly the gun does not always exhibit the problem. Several boxes of cartridges were fired between each incident without a discharge. If possible please do not adjust the trigger pull. At its present pull, with my favorite load, the rifle shoots 1/2" groups at 100 yards.