

RECEIVING AND ESTIMATING REPORT

BARBER - Kinzer PPS

GAL RE0004025

ORDER
R 92-20714

IAL JM	CUSTOMER ORDER NO.		ATTN J STEKL BOTT F OF MTS ONLY CLASSIC	
E RECEIVED 9/01/92	DATE OPENED 10/08/92	DATE CODE OI 7-88	SERIAL NUMBER C6280426	NEW SERIAL NUMBER
ESSORIES W/STUDS		SCOPE BASE		MODEL AND GRADE 700 35 WHELEN

M:	SHIP TO:
RAISLER, LOU 8546 W HOMOSASSA TRAIL ST #3 HOMOSASSA FL 32448	RAISLER, LOU 8546 W HOMOSASSA TRAIL ST #3 HOMOSASSA FL 32448

CUST NO:067857 C.O.D.

QUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
CONDITION					REPAIR CHARGE:
NEW					EXCISE:
IGHTLY WORN					TAX
WORN					INSURANCE
ERY WORN					UPS
UNREPAIRABLE					PARCEL POST
DARRIED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
GER GROUP		B3			E1	F1
T ASSY.		B4		D1	E3	F3
REL ASSY.		B5		D2	E4	F4
ASSY.			C1	D3	E5	F5
JD			C2			
AL						

Cannot duplicate complaint after many attempts - Trigger assembly operating properly. However, disassembly of the revealed trigger assembly components have been tampered with outside factory (sealant missing from all vent screws) 1) insufficient rear engagement, 2) insufficient over travel engagement 4# rear off .010" stock is radial at front guard screw location - insufficient clearance for screw

COMMENTS	
1) Offer replacement trigger assembly at nominal cost, as good will gesture	
2) Replace stock at N/C	
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	TEST
TARGET	PATTERN
DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

BARBER - Kinzer PPS GAL RE0004025

PPS 04020