

our specifications at .0115". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed. Inadvertent contact with the trigger while releasing the safety could cause a rifle to fire, which will occur with all popular bolt action rifles.

Since we found your firearm to function properly in every respect, we are prepared to return it in its present condition. However, if you so desire, we offer the following alternatives: (1) Install a new trigger assembly with the present safety lever for \$35.00; (2) Install a trigger assembly without a bolt-lock which allows raising the bolt handle while the safety lever is in the "on-safe" position for \$35.00.

Should you desire one of the alternatives set forth, please include a check in the above amount made out to Remington Arms Company, Inc., with your response marked to my attention. We will await your decision and reply.

Thank you for affording us the opportunity to examine your rifle and report our findings.

Sincerely,

J. A. Stahl