

RECEIVING AND ESTIMATING REPORT

CUST NO: 047992 C.O.D		COMMENTS ENTIRE GUN IS PAINTED			
INITIAL CS	CUSTOMER ORDER NO.				
DATE RECEIVED 8/20/91	DATE OPENED 08/22/91	DATE CODE DB-1/1	SERIAL NUMBER B6324614	MODEL AND GRADE 700 308	ORDER R 91-16474
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS	
FROM:			SHIP TO:		
ROBINSON, MARK RT 3 BOX 181A CAMERON USA			ROBINSON, MARK RED X MOTORE 509 NORTHLAND DR CAMERON USA		
MO 64429			MO 64429		
COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 9-9-91
			VIA UPS		

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

then safety is disengaged rifle sometimes fires, when closing bolt it will discharge.

MAIN FAULT

Cannot duplicate above complaints. However, trigger assembly has been improperly adjusted outside factory as evidenced by redant missing from adjustment screws. Trigger pull below spec at 24 # 2) over-travel insufficient. Cam-follower has been installed in after-market synthetic stock - safety lever will not move fully rearward because of contact in stock inletting.

Send repair quotation for new trigger assembly.

REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90