

July 25, 1992

Repair Serv. Dept.

RE: Rem Mod. 700 L.H.

Would you please evaluate the mechanical condition of the Safety (Firing Mechanism) & trigger.

I have tried to adjust the trigger pull, but cannot. Gun will fire by the motion of racking the bolt.

Would you please make the necessary repairs you feel is appropriate. I can be contacted by phone or mail at the following:

John F. Roper

John Roper

2284 Cody Estey Rd.

Rhodes, ME. 48652

Home: 517-879-3616

Work: 517-636-4976