

RECEIVED

OCT 21 1985

ARMS SERVICE

October 15, 1985

Dear Sir:

On August 27, 1984 I purchased an Remington 270 A.D.L. Rifle for Pennida in Fergus Falls Minn. In November of 1984 my rifle screwed up, pushed the safety switch to fire, fire arm discharged, did this procedure twice. This happened when I was on a hunting trip in Washington. Gunsmith repaired the rifle.

This past week on October 9th, 85 I was checking my rifle out once again. Put a single shell in the chamber, push the safety to fire gun discharged, damn near blew my foot off.

On Wednesday 16th of October I took my 270 to gunsmith once again to get overhauled.

My rifle is as follows:

Remington 270 A.D.L.

Serial no. B65 56 861.

As I thought I would drop a line to your office about the faulty safety. I hope all 400 series rifles are not like this.

You folks make fine rifles and shot guns but beginning to wonder whether to buy any future firearms with thought of defects.

Sincerely,

Jerry Rosenthal (Lawrence M.)
Rt#1 Box 411
Richville, Minn. 56576.