

RECEIVING AND ESTIMATING REPORT ✓

INITIAL CS		CUSTOMER ORDER NO.		COMMENTS ATTN J STEKL			
DATE RECEIVED 10/04/90	DATE OPENED 10/12/90	DATE CODE KY 5-74	SERIAL NUMBER 6749628QQQ	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-26	
ACCESSORIES		L/SIGHTS		SCOPE BASE			
FROM:				SHIP TO:			
ROYAL ARMS 5608 KITSAP WAY SUITE 1 BREMERTON WA 98312				ROYAL ARMS 5608 KITSAP WAY SUITE 1 BREMERTON WA 98312			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☐ MISUSED ☒ MARRED					
CUSTOMER'S REQUEST					

"It has had 3 accidental discharges when safety is released"

MAIN FAULT: Cannot duplicate complaint; Trigger assembly and safety operate properly. However, assembly contains an excessive amount of lubrication (oil) - a cold temperature, this accumulation could cause trigger parts to freeze upon future problems. Trigger pull 4 pounds, rear-lyt. 68"

PARTS	Offer to clean present trigger assembly. If it will better restore confidence in the rifle, offer to replace trigger assembly at 500.00 plus as guarantee of good-will.					
	10/15/90 JH					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY