

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS			
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
22/90	08/31/90	CR 4-68	041591	788 243	R 90-22934
L/WOOD		L/SIGHTS			

SHIP TO:	
RUSH CREEK GUN SHOP 7843 U S 20 WEST STOCKTON IL 61085	RUSH CREEK GUN SHOP 7843 U S 20 WEST STOCKTON IL 61085

ITEM NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

--	--	--	--	--	--

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED
------------	------------------------------	--	------------------------------------	----------------------------------	---------------------------------

R'S REQUEST

"GUN FIRES upon closing"

cannot duplicate complaint - however, examination of trigger assembly did show it contains a sticky lubrication residue of maybe rusty inside - bottom of receiver mating.

Send quotation to clean trigger assembly if it is possible; if not, send quotation for new trigger assembly.

9/14/90
JAC

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88

OFFICE COPY