

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS		#36	
DATE RECEIVED 10/25/96	DATE OPENED 10/29/96	DATE CODED KI 5-88	SERIAL NUMBER C4252382	MODEL AND GRADE 700 36-86	ADL/LS	ORDER NO.	
ACCESSORIES 47 STUDS							

FROM:

RUTTY, STEPHEN E
RD #2
BOX 240
CANTON PA 17724

SHIP TO:

RUTTY, STEPHEN E
RD #2
BOX 240
CANTON PA 17724

17724

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☒ LIKE NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"i am moving the safety across the rifle to fire"

MAIN FAULT

Tripin assembly rusted from unknown source.
Internal tripin parts not moving freely

PARTS

Replace tripin assembly at no-charge, as gesture of good-will

REPAIRMAN [Signature]	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV 7/90