

REM MOD 700 SS SER # 56203868

OWNER: JOHN C. SANTO

PO BOX 557

PRAIRIE CITY, OR. 97869

BUS. PHONE: 503-820-3334 · 7AM-4PM WEEKDAYS

HOME PHONE: 503-820-3635

* UPS WILL DELIVER - THERE IS NO HOME MAIL DELIVERY

~~XXXXXXXXXXXX~~
~~XXXXXXXXXXXX~~
- BROWN HARD GUN
CASE

⇒ DEFECTIVE TRIGGER/SAFETY MECHANISM.

THIS IS A BRAND NEW RIFLE — PURCHASED AUGUST 1992

ONLY 10 ROUNDS HAVE BEEN FIRED THRU THIS RIFLE,
AFTER ABOUT THE 5TH ROUND, I NOTICED THE TRIGGER PULL
BECAME HARDER

ON ROUND 10, ROUND WAS CHAMBERED, RIFLE WOULD NOT FIRE
NO FIRING PIN DROP. SAFETY SWITCH WOULD NOT MOVE TO "S."
BOLT WAS RAISED AND PULLED BACK.

SAFETY SWITCH WAS MOVED TO "S" POSITION

BOLT WAS ENGAGED WITH LIVE ROUND. FINGER OFF TRIGGER.

SAFETY SWITCH WAS MOVED TO "F" POSITION — CAUSED RIFLE
TO FIRE WITHOUT ENGAGING TRIGGER.

LIVE FIRING WAS IMMEDIATELY HALTED

WITH SAFETY ON "F", ENGAGE BOLT, RIFLE WILL NOT FIRE,

SAFETY WILL NOT MOVE TO "S". REMOVE BOLT — SAFETY MOVES.

WITH SAFETY ON "S" ENGAGE BOLT, RIFLE WILL NOT FIRE.

WITH FINGER OFF TRIGGER, BY MOVING SAFETY FROM "S"
TO "F" CAUSES FIRING PIN TO DROP.

RIFLE GROUPS 4" AT 100 YDS — HORRIBLE!

LOOK AT FIT OF REAR OF RECEIVER/ACTION WITH STOCK — VERY CRUDE!

LOOK AT CUT OF STOCK UNDER BARREL — VERY UNEVEN.