

Rev. 2-15-61

M/700 Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 016319
OUTSIDE WORK: FIRING PIN HEAD GROUND DATE: 8-24-72
ON BOTTOM FROM: SCHOELLKOPF CO.
FIRED AMMO TYPE: - DALLAS, TEXAS
& CONDITION: _____ GUN #: 6481075
PROOF: R.E.P.-M ^{ASSEMBLER 72} INSP.: 9 TEST: 53 CODE: EV = 10/41
HEADING: - G.K./CAL.: 7MM M03
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

ENGAGEMENT (HORIZONTAL) BETWEEN SEAR AND TRIGGER
CONNECTOR .025 (VERTICAL ENGAGEMENT ZERO BECAUSE
OF THE GROUND FIRING PIN HEAD).

COMPLAINT: "WITH STOCK OFF GUN FOLLOWS DOWN."

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS THAT THE CUSTOMER GROUND THE
FIRING PIN HEAD REDUCING THE FIRING PIN HEAD-SEAR
ENGAGEMENT TO ZERO, CAUSING THE FOLLOW DOWN.