

May 3, 1988
Box 141
South Lindseley, UT 84515

Roger Potter
Remington Arms Co
14 Hoosier
Indian, IN 46357.

Dear Sir;

Enclosed in the rifle per
your telephone call of May 2, 1988.
It has fired twice for no apparent
reason, (1) when loading and lowering
the bolt and (2) when loaded and
releasing the safety.

I fired four rounds and it
malfunctioned once in four rounds;
when lowering the bolt to firing position.

Sincerely
Mr. Rollin Severance